MAYES TESTING ENGINEERS, INC.

June 18, 2007

City of Seattle DPD PO Box 34019 Seattle, WA 98104-4019

JUL 2 3 2007

PRELIMINARY FINAL LETTER

Permit # 750149

Lynnwood Office 20225 Cedar Valley Road Suite 110 Lynnwood, WA 98036 ph 425.742.9360 fax 425.745.1737

Tacoma Office 10029 S. Tacoma Way Suite E-2 Tacoma, WA 98499 ph 253.584.3720 fax 253.584.3707

Portland Office 7911 NE 33rd Drive Suite 190 Portland, OR 97211 ph 503.281.7515 fax 503.281.7579

Attn.: Quality Control

Re: Rainier Commons Building 3100 Airport Way South Seattle, WA

MTE Project No. E5230

This is to advise you that special inspections are complete for the referenced project with the exception of stairway #6. We understand that a temporary C.O. is requested and that all items are complete except for stairway #6. This letter addresses the remainder of the building. The following inspections were required:

- 1. Reinforced Concrete (cast in place)
- 2. Shotcrete
- 3. Reinforced CMU Masonry
- 4. Structural Steel Erection (Incomplete)
- 5. Steel Decking
- 6. Prefabricated Steel Stair Erection
- 7. Spray-applied Fire Resistive Materials
- 8. Seismic Tie Installation
- 9. Installation of Holdown System
- 10. Diaphragm Nailing
- 11. Epoxy Grouting
- 12. Expansion Anchor Bolt Installation
- 13. Anchor Bolt Installation
- 14. Epoxy-Grouted Anchor Bolt Installation
- 15. Nail Connection per 3/S6.1

Special inspections were performed for the following activities and copies of reports have been sent to you.

- 1. Reinforced Concrete (cast in place)
- 2. Shotcrete
- 3. Reinforced CMU Masonry
- 4. Structural Steel Erection
- 5. Steel Decking
- 6. Spray-applied Fire Resistive Materials
- 7. Seismic Tie Installation
- 8. Installation of Holdown System 15, 552
- 9. Diaphragm Nailing
- 10. Epoxy Grouting
- 11. Expansion Anchor Bolt Installation
- 12. Anchor Bolt Installation
- 13. Epoxy-Grouted Anchor Bolt Installation
- 14. Nail Connection per 3/S6.1

Page 1 of 2

To the best of our knowledge, all work inspected conformed to DPD approved plans, specifications, Director's Rules, SBC and related codes and/or verbal or written instructions from the Engineer of Record.

Sincerely, MAYES TESTING ENGINEERS, INC.

Timothy, G. Beckerle, P.E. Branch Manager

Cc: Hertzal Hazan - Ariel Development LLC
Ed Linardic – LDG Architects
Rich Putz - Ethan Construction

Liz Fekete, P.E. - Swenson Say Faget Engineers

TGB:rsm